

VIA EMERY EXPRESS



75
AT&T

1 Oak Way
Berkeley Heights, NJ 07922-2727
201 771-2000

May 12, 1989

109888

Mr. William D. Steuteville
U.S. Environmental Protection Agency
841 Chestnut Building
Philadelphia, PA 19107

RE: Monthly Inspection
C & D Recycling Site
Foster Township, PA

Dear Bill:

Enclosed is the monthly inspection and maintenance report for the
C & D Recycling Site.

Sincerely,

Joe Chikowski
Senior Engineer

JTC/mhl

Enclosure

AR400656

B. E. S.

ENVIRONMENTAL SPECIALISTS INC.

And 24-Hour Emergency Response

P.O. BOX 1801

KINGSTON, PENNSYLVANIA 18704

Phone: (717) 779-5316

ORIGINAL
12-00

May 5, 1989

A T & T Corporation
One Oak Way, Room 5U-2WA143
Berkeley Heights, New Jersey 07922-2727

Attention: Joseph T. Chikowski


Dear Mr. Chikowski;

Enclosed please find the completed copy of the site inspection report for the May site visit to the C & D Recycling site. All maintenance and corrective activities performed during this site inspection have been listed.

Once again, thank you for your continued interest in the quality field services provided by B.E.S. Environmental Specialists, Inc.

Please feel free to contact our offices should you have any questions about this report or any additional site services.

Yours truly,


David Fife

DF/lph

C&D RECYCLING SITE
MONTHLY INSPECTION AND MAINTENANCE REPORT

ORIGINAL
(Red)

SECTION I - GENERAL

1. Name of Company Performing Inspection:

B.E.S. Environmental Specialists, Inc.

2. Name of Inspector:

Michael George

3. Beginning Date of this Inspection:

May 4, 1989

4. Site Map Reviewed:

YES

5. Previous Inspection and Maintenance Report Reviewed:

YES

6. Date of Previous Inspection:

April 10, 1989

7. Were any maintenance activities required on previous inspection report in which corrective action was not taken? NONE If so, which activities were not completed.

AR400658

ORIGINAL
(Red)

SECTION II - FIELD INSPECTION

(A site map must be taken to site.)

1. Site Security Fence: Walk Perimeter - Note Location of Deficiencies on Site Map.
 - o Warning Signs Intact? Yes X No ____ If Not, Action Taken
 - o Chain Link Fence Intact? Yes X No ____ If Not, Action Taken
 - o Barbed Wire Intact? Yes X No ____ If Not, Action Taken
 - o Gates Intact? Yes X No ____ If Not, Action Taken
 - o Tension Wire Intact? Yes X No ____ If Not, Action Taken
 - o Chain & Padlocks Intact? Yes X No ____ If Not, Action Taken
 - o Additional Observations (Erosion under fence, loss of post support, etc.).

AR400659

2. Temporary Ash Cover: Inspect all three piles individually.

Northern Pile

- o Plastic Cover Intact? Yes X No If Not, Action Taken
- o Tire Hold-Down Intact? Yes X No If Not, Action Taken
- o Perimeter Drainage Channel Intact? Yes No X If Not, Action Taken
Drainage channel was re-established
- o Additional Observations.

Central Pile

- o Plastic Cover Intact? Yes X No If Not, Action Taken
- o Tire Hold-Down Intact? Yes X No If Not, Action Taken

AR400660

- o Perimeter Drainage Channel Intact? Yes ☐ No ☒ If Not, Action Taken
Drainage channel was re-established
- o Additional Observations.

Southern Pile

- o Plastic Cover Intact? Yes ☒ No ☐ If Not, Action Taken
- o Tire Hold-Down Intact? Yes ☒ No ☐ If Not, Action Taken
- o Perimeter Drainage Channel Intact? Yes ☐ No ☒ If Not, Action Taken
Drainage channel was re-established
- o Additional Observations.

- 3. Drainage Channel: Walk entire length - Note location of deficiencies on Site Map.

- o Riprap Layer Intact? Yes ☒ No ☐ If Not, Action Taken

AR400661

- o Geotextile Intact? Yes X No If Not, Action Taken
- o Subgrade providing adequate support to bottom and sideslopes? Yes X
No If Not, Action Taken
- o Channel Unobstructed? Yes X No If Not, Action Taken
- o Additional Observations.

4. Silt Fence: Walk all reaches - note location of deficiencies on Site Map.

- o Silt Fence Intact? Yes X No If Not, Action Taken
- o Fabric Secured to Posts? Yes No X If Not, Action Taken
Fabric was re-attached
- o Fabric Entrenched Into Soil? Yes No X If Not, Action Taken
Wash-outs were repaired
- o Runoff Flowing Through Fence and Not Around Fence. Yes ✓ No If
Not, Action Taken
- o Additional Observations.

*Added not shown
on original etc.*

Note: Deficiencies in silt fence are noted on the site map as requested.

AR400662

5. CMP Drainage Pipe Downdrain: Walk entire length - note location of deficiencies on Site Map.

- o Pipe Connections Intact? Yes X No ____ If Not, Action Taken
- o Anchor Bars Embedded and Intact? Yes X No ____ If Not, Action Taken
- o Outlet Area Intact? Yes X No ____ If Not, Action Taken
- o Pipe Outlet Unobstructed? Yes X No ____ If Not, Action Taken
- o Additional Observations.

AR400663

SECTION III - SUMMARY

Date Inspection and Maintenance Activities were completed:

May 4, 1989

List of maintenance activities which were not completed at the time that this report was prepared:

Michael George 4 May '89

SIGNATURE OF INSPECTOR/DATE

AR400664

